UL Mark Surveillance Flowchart

UL

Field Engineer meets with customer contact at the manufacturing location

↓

Conduct review of documentation needed to perform surveillance visit

↓

Walk through of facilty is conducted

↓

UL Labeled or intended to be labeled product is identified — **NO** → Production Ready (PRV) Report is issued

YES ↓

Inspection of selected product to FUS Requirements begins

↓

Label Records and Production Records are Reviewed	Product attributes are verified and and measurements taken when applicable	Required Tests are witnessed	Traceability of Parts is veriifed	Calibration of IMTE verified
Link to Label Center	Link to Resources	Link to Resources	Link to Resources	Link to Resources

↓

Compliance to Requirements? — **NO** → Variation Notice Issued

Link to Resources

YES ↓

Inspection Report Issued

↓

Inspection Concludes

Other Useful Resources:

UL Product IQ

Link to MyUL Portal

For more information, please contact your local UL field engineer.